

Attorney Docket No. 9310-38

cgc
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Re: Kreuwel et al.

U.S. Patent No.: 6,764,859 *B1*

Application Serial No.: 10/031,222

Issued: July 20, 2004

Filed: June 4, 2002

For: *Device and Method for Mixing Magnetic Particles with a Fluid*

Date: October 6, 2004

Certificate
OCT 15 2004
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450


REQUEST FOR ENTRY OF CERTIFICATE OF CORRECTION UNDER
35 U.S.C §254 AND 37 C.F.R. §1.322

Sir:

The Assignee of record for the above-referenced patent hereby requests, pursuant to 35 U.S.C §254 and 37 C.F.R. §1.322, that a Certificate of Correction be issued. This request is made in order to correct the mistakes incurred through the fault of the U.S. Patent and Trademark Office. No fee is believed due. However, the Commissioner is authorized to charge any deficiency or credit any overpayment to Deposit Account No. 50-0220.

The mistakes appearing in the patent are set forth with corrections on the Certificate of Correction enclosed herewith, with an additional copy thereof and a return post card.


Respectfully submitted,


Julie H. Richardson
Registration No. 40,142

Myers Bigel Sibley & Sajovec, P.A.
P. O. Box 37428
Raleigh, North Carolina 27627
Telephone: (919) 854-1400
Facsimile: (919) 854-1401
Customer No. 20792

Certificate of Mailing under 37 CFR 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on October 6, 2004.


Monica L. Croom

OCT 18 2004

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,764,859 *B1*
DATED : July 20, 2004
INVENTOR(S) : Kreuwel et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

Column 9, line 21 should read -- array in concert back and forth between magnet arrays. --

Column 10, lines 49-50 should read -- array forward while moving the magnets in the second magnet array rearward so that adjacent containers in the first --

Column 10, line 61 should read -- container array so that containers in the first container array are --

MAILING ADDRESS OF SENDER:
Myers, Bigel, Sibley & Sajovec
P.O. Box 37428
Raleigh, NC 27627

PATENT NO. 6,764,859 *B1*
No. of additional copies: _____

⇒
This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you are required to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

OCT 18 2004